


End of Life of Ovarro "TBox" Hardware  
at 01/01/2022



LEGEND

Repair According to the availability of components in the future, in relation to the volume of repairs, it might not be possible to repair. In such case we might propose a replacement of material.  
 Firmware All efforts are put in place to maintain the product; it might not be possible due to third party. In such case we might propose a replacement of material  
 Assistance The period for which you can receive help, support and assistance in using the product

with ending color, it corresponds to the last year of availability for the associated service  
 with ending dots, it corresponds to the minimum year of availability for the associated service

Hardware	Start Date	End Of Sales	Replacement	Support	2016	2017	2018	2019	2020	2021	2022	2023	2024	2025	2026	2027	2028	2029	2030	2031	2032	2033	2034	2035	2036
Legacy products																									
<i>click &lt;-&gt;</i>																									
Current Products																									
MS-CPU32	2007	2015	MS-CPU32-S2	Repair																					
				Firmware (2)																					
				Assistance																					
MS-CPU32-X	2010	2015	No	Repair																					
				Firmware (2)																					
				Assistance																					
LT2/TG2 - 4W	2019		-	Repair																					
				Firmware																					
				Assistance																					
- 3G	2012	2018	LT2/TG2 - 4W	Repair																					
- 3E (3)	2017		-	Repair																					
- 4E	2018	2019	LT2/TG2 - 4W	Repair																					
- 4N (4)	2017		-	Repair																					
- S	2017		-	Repair																					
RM2	2012		-	Repair																					
				Firmware																					
				Assistance																					
MS-CPU32-S2	2015	-	-	Repair																					
				Firmware																					
				Assistance																					
<i>click &lt;-&gt;</i>																									
MS Modules				Firmware (5)																					
				Assistance (5)																					
MS-PS230			-	Repair																					
MS-PS-AC30W			-	Repair																					
MS-PS-DCN			-	Repair																					
MS-CHARGER			-	Repair																					
MS-PSTN			-	Repair																					
MS-GSM-2G			MS-GSM-4W	Repair																					
MS-GSM-3G	2012	2017	MS-GSM-4W	Repair																					
MS-GSM-4E	2018	2019	MS-GSM-4W	Repair																					
MS-GSM-4W	2019		-	Repair																					
MS-ETHER-1		2009	MS-ETHER-4	Repair																					
MS-ETHER-4			-	Repair																					
MS-SERIAL			-	Repair																					
MS-GPS			-	Repair																					
MS-16DI			-	Repair																					
MS-48DI			-	Repair																					
MS-16DO			-	Repair																					
MS-16DIO			-	Repair																					
MS-COMBO-1			-	Repair																					
MS-RELAY			-	Repair																					
MS-10DIHS			-	Repair																					
MS-8AIVC		2020	MS-8AIVC2	Repair																					
MS-8AIVC-2	2020		-	Repair																					
MS-8RTD		2017	MS-8RTD	Repair																					
MS-8RTD	2020		-	Repair																					
MS-4AI420			-	Repair																					
MS-8AI420			-	Repair																					
MS-4ADVC			-	Repair																					
MS-IO-SIMUL			-	Repair																					
<i>click &lt;-&gt;</i>																									
<i>click &lt;-&gt;</i>																									
<p>(1) some parts cannot be repaired, ie. Power Supply, Booster, PSTN modem, ...</p> <p>(2) LINUX 2.6.27 cannot be upgraded, then some new features could not be available</p> <p>(3) only model that still supports CSD. Available until end of stock</p> <p>(4) model for North America (except AT&amp;T)</p> <p>(5) on all -MS modules</p>																									