ASACLEAN[™] CHEMICAL GRADES EXTRUSION BLOW MOLDING PURGING INSTRUCTIONS For Resins 175°C – 360°C (345°F – 680°F)

- 1. Empty the system of the production resin, and make sure the feed areas are clean.
- 2. If possible, and safe, raise heats in all zones after the screw and barrel to at least 230°C (450°F). Best results will be obtained at 260°C to 315°C (500°F to 600°F). Temperatures of outboard heads (in multiple head setups) should be 30°C (50°F) hotter than inboard heads. Do not exceed 360°C (680°F). Do not use ASACLEAN NCF grade for extrusion blow molding.

If purging a heat-sensitive resin, do not exceed the safe processing temperature of the material. This purge procedure may need to be repeated at elevated temperatures to remove all contamination.

- 3. Manually clean and cap all barrel vents and increase temperatures in the decompression zones by 15°C (25°F), and make sure the feed areas are clean.
- 4. Flush the machine by running 1-4 system volumes of clean, natural blow molding grade HDPE. It is best to use an HDPE that is stiffer than the production resin.
- 5. Empty the system of the flush resin and add ASACLEAN at normal screw speed until the purge extrudes uniformly from the head(s). If using accumulators, increase the setpoints by 10% and cycle on automatic 2 to 4 times to ensure complete filling.
- 6. Turn the screw at minimum controllable rpm for a 30-minute heat soak. ASACLEAN is heat activated, so expansion will occur during the heat soak. For reciprocating screws, stop the screw during the soak phase, and take a shot every 5 minutes to ensure the head stays full.
- 7. Empty the screw and barrel.
- 8. If the last of the purge carries contamination, repeat steps 5-7.
- 9. Wait 5 minutes with an empty barrel for the ASACLEAN residue to break down.
- 10. Change temperatures to the profile required for the next material.
- 11. When safe, displace the ASACLEAN with the next resin.
- 12. Begin production under normal processing conditions.

Technical Questions?

To request detailed technical bulletins or technical support, contact us at Asahi Kasei Asaclean Americas Inc.

| Phone: (800) 787-4348 / (973)257-1999 | Fax: (973) 257-1011 |
|---------------------------------------|-----------------------------------|
| Website: <u>www.asaclean.com</u> | E-mail: <u>sales@asaclean.com</u> |